

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name	2. Date Prepared	3. Time Prepared
		Kalamazoo River/Enbridge Oil Spill	10/23/2012	1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/18/2012 – 0700, 10/25/2012	
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> <li>• Boat safety meeting at C0.4 boat launch. Launch.</li> <li>• MP5.15 LDB area where sheen and tar globs were observed.</li> <li>• MP5.25 LDB sheen and tar globs were observed.</li> <li>• MP5.35 LDB sheen and tar globs were observed.</li> <li>• MP5.63 LDB sheen and tar globs were observed.</li> <li>• Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.</li> <li>• Ceresco Dam observed the sweep boat arriving to begin debris removal from the control point boom.</li> <li>• MP5.75 RDB area where sheen and tar globs were observed.</li> <li>• MP5.55 RDB sheen and tar globs were observed.</li> <li>• MP5.25 RDB area where sheen and tar globs were observed.</li> <li>• MP5.25 RDB sheen and tar globs were observed.</li> <li>• MP5.15 RDB sheen and tar globs were observed.</li> <li>• MP4.75 LDB sheen and tar globs were observed.</li> <li>• MP14.65 LDB sheen and tar globs were observed.</li> <li>• MP15.5 South Mill Pond no sheen observed.</li> <li>• MP15.65 RDB North Mill Pond sheen observed in the river channel.</li> <li>• MP15.75 RDB North Mill Pond sheen was observed accumulating.</li> <li>• MP15.0 LDB sheen and tar globs where observed.</li> <li>• MP14.75 LDB sheen and tar globs where observed.</li> <li>• Morrow Lake Delta Gate E observed a crew removing debris from the control point boom.</li> <li>• Morrow Lake North Cove sheen and tar globs were observed.</li> <li>• Morrow Lake Delta Gate F south sheen and tar globs were observed.</li> <li>• Morrow Lake Delta Gate C sheen and tar globs were observed.</li> <li>• Morrow Lake Delta Gate C sheen and tar globs were observed collecting along the downstream side of the boom.</li> <li>• Morrow Lake Delta Gate B sheen and tar globs were observed.</li> </ul>			
1600	Finish up inspections at E4 boat launch. Return to ICP.			

9. Prepared by (Name and Position)

Matthew Haak, Situation Unit Leader, USEPA-START