

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, October 25, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	58.84	57.85
Ceresco Dam Containment Boom	58.03	58.90

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area sheen observed.



2. Source area sheen observed.



3. Frac-Tank City observed standing water.



4. Ceresco Dam overview.



5. Ceresco Dam control point boom.



6. MP5.35 LDB spontaneous sheen observed.




7. MP5.45 LDB spontaneous sheen observed.



8. MP5.63 LDB spontaneous sheen observed.



9. Ceresco Dam observed a crew preparing to remove debris from the control point boom.



10. Ceresco Dam observed sheen and tar globs collecting along the boom.



11. Ceresco Dam observed sheen and tar globs collecting along the boom.



12. Ceresco Dam observed sheen and tar globs collecting along the boom.



13. MP5.55 RDB area where spontaneous sheen and tar globs observed.




14. MP5.25 RDB area where spontaneous sheen and tar globs observed.



15. MP5.25 RDB spontaneous sheen and tar globs observed.




16. MP5.25 RDB spontaneous sheen and tar globs observed.



17. MP7.75 I observed an RI crew.



18. MP7.75 I observed an RI crew.



19. MP10.0 LDB observed an RI crew.



20. MP10.40 RDB sediment trap.



21. MP10.5 LDB sediment trap.



22. MP10.75 LDB Sediment Trap.



23. MP14.75 Sediment Trap.



24. MP19.25 Sediment Trap.



25. MP19.25 Sediment Trap observed sheen collecting.



26. MP21.5 Oxbow Sediment trap.



27. MP26.0 RDB Sediment Trap.



28. MP28.25 Oxbow Sediment Trap.



29. MP30.8 Sediment Trap.



30. MP33.0 A&B Sediment Trap.



31. MP36.10 Sediment Trap.



32. Morrow Lake Delta.



33. Morrow Lake Delta observed a crew removing debris from Gate B.



34. Morrow Lake Delta observed a poling crew.



35. Morrow Lake Delta observed a poling crew.



36. Morrow Lake Delta Gates E & F.