

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, November 7, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. Morrow Lake Delta Gate E observed a crew inspecting the curtain.



2. MP5.35 LDB sheen and tar globs observed.



3. MP5.45 LDB sheen and tar globs observed.



4. MP5.45 LDB sheen and tar globs observed.



5. MP5.55 LDB sheen and tar globs observed.



6. MP5.55 LDB sheen and tar globs observed.



7. Ceresco Dam observed sheen collecting along the control point boom.



8. Ceresco Dam observed sheen collecting along the control point boom.



9. Ceresco Dam observed sheen collecting along the control point boom.



10. Ceresco Dam observed sheen collecting along the control point boom.