

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, November 12, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	55.95	56.89
Ceresco Dam Control Point Boom	50.95	49.75
C5 Boat Launch Gauge	52.72	54.68
E4 Boat Launch Gauge	51.81	52.31



1. MP5.20 LDB Area where sheen and tar globs were observed.



2. MP5.20 LDB spontaneous sheen and tar globs observed.



3. MP5.20 LDB spontaneous sheen and tar globs observed.



4. Ceresco Dam observed a crew surveying an anchor point for the bathymetry survey.



5. MP5.5 Center channel observed sheen and tar globs.



6. MP5.5 Center channel observed sheen and tar globs.



7. MP4.75 LDB area where sheen and tar globs were observed.



8. MP4.75 LDB sheen and tar globs observed.



9. MP4.5 LDB Area where sheen and tar globs observed from boat agitation.



10. MP4.5 LDB sheen and tar globs observed from boat agitation.



11. MP4.5 LDB sheen and tar globs observed from boat agitation.



12. MP4.5 LDB sheen and tar globs observed from boat agitation.




13. MP15.0 area where sheen and tar globs were observed in the river channel.



14. MP15.0 sheen and tar globs observed in the river channel.



15. MP15.0 RDB South Mill Pond area where sheen and tar globs were observed.



16. MP15.0 RDB South Mill Pond sheen and tar globs observed.



17. MP15.0 RDB South Mill Pond sheen and tar globs observed.



18. MP15.25 RDB South Mill Pond sheen and tar globs observed.



19. MP15.25 RDB South Mill Pond sheen and tar globs observed.



20. MP14.75 LDB area where sheen and tar globs were observed.



21. MP14.75 LDB sheen and tar globs observed.



22. E4 Boat Launch Bathymetry team departing.



23. Morrow Lake Delta Gate A observed the Bathymetry team.



24. Morrow Lake Delta Gate A observed the Bathymetry team.



25. Morrow Lake Delta Gate A observed the Bathymetry team.



26. Morrow Lake Delta Gate A observed the Bathymetry team.