

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, November 16, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	38.29*	40.53*
C3.2 Boat Launch Gauge	38.62	41.36
E4 Boat Launch Gauge	43.59	45.10

*Temperature was taken at MP5.75 RDB, due to access being restricted at C0.4 during opening days of hunting season.



1. Ceresco Dam Control Point Boom.



2. MP5.63 RDB. Thin layer of ice observed along shoreline during morning inspection.



3. MP5.80 LDB observed very thin shoreline ice along southwest corner at Ceresco Dam.



4. MP15.25 South Mill Pond as observed from Burnham Street Bridge.



5. MP15.25 South Mill Pond ice observed melting.



6. Morrow Lake North Cove.



7. Morrow Lake North Cove ice observed in southwest nook in cove.



8. Morrow Lake Delta Gate E South observed a Bathymetry team.



9. Morrow Lake Delta observed Bathymetry survey transit.



10. Morrow Lake Delta Gate B observed Bathymetry team.



11. Morrow Lake Delta observed sweep boat crew.