

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Friday, November 23, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Ceresco Dam control point boom, no sheen or ice observed.



2. Ceresco Dam control point boom, no sheen or ice observed.



3. Ceresco Dam MP5.75 RDB sheen observed within the vegetation.



4. Ceresco Dam MP5.75 RDB sheen observed within the vegetation.



5. MP15.5 South Mill Pond no ice or sheen observed.