

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, November 26, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	37.71	41.56
Ceresco Dam Control Point	36.55	42.95




1. MP5.5 LDB, no ice or sheen observed along river shoreline in this area.



2. Ceresco Dam trestle, no sheen observed.



3. MP5.63 RDB, observed thin layer of ice on downstream side of trestle.



4. MP5.63 LDB, no sheen or ice observed in this area.



5. Ceresco Dam control point boom, some debris and sheen observed.



6. Ceresco Dam control point, sheen observed mingled with debris in containment.



7. Ceresco Dam control point, sheen observed within containment.



8. MP 15.5, south side of Mill Pond. No sheen observed, some ice observed in stagnant water in eastern side of Mill Ponds.



9. MP 15.5 north Mill Pond. Utility excavation work continues on northern side of Burnham Street Bridge. No sheen observed.



10. Morrow Lake Delta, no ice observed forming within the neck of the delta.



11. Morrow Lake Delta observed the anchor poles and boom in place.



12. E4.0 boat launch. No sheen or ice observed.