

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, December 8, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	42.21	42.92
Ceresco Dam Control Point Boom	41.70	44.68
E4 Boat Launch Gauge	42.37	43.42

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. Morrow Lake observed a sweep boat in the north cove.



2. MP28.25 Sediment trap observed bathymetry teams.



3. MP28.25 Sediment trap observed bathymetry teams.



4. MP28.25 Sediment trap observed deployed snare boom to collect sheen and tar globs generated by the bathymetry teams.



5. MP19.25 Sediment trap observed a bathymetry team.



6. MP19.25 Sediment trap observed a bathymetry team.



7. MP19.25 Sediment trap observed a bathymetry team.



8. MP15.25 South Mill Pond no sheen observed.



9. MP5.63 LDB area where sheen and tar globs were observed.



10. MP5.63 LDB sheen and tar globs observed.



11. MP5.63 LDB sheen and tar globs observed.



12. Ceresco Dam control point boom.



13. Ceresco Dam control point boom observed sheen and tar globs collecting along the boom.



14. Ceresco Dam control point boom observed sheen and tar globs collecting along the boom