

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, December 11, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source Area observed the pipeline installation preparation work continuing at the source area and across Talmadge Creek.



2. Frac Tank City, no decon operations observed.



3. Ceresco Dam impoundment observed a bathymetry crew.



4. Ceresco Dam impoundment observed a bathymetry crew.



5. MP5.63 LDB & RDB observed ice forming.




6. MP5.63 LDB observed ice forming.



7. MP10.4 RDB Sediment Trap observed ice beginning to form.



8. MP10.5 LDB Sediment Trap observed ice beginning to form.



9. MP12.25 LDB observed an RI crew.



10. North and South Mill Ponds observed ice forming.



11. MP15.25 South Mill Pond no sheen observed.



12. MP21.5 Sediment Trap observed a bathymetry crew.



13. MP21.5 Sediment Trap observed a bathymetry crew.



14. MP26.25 Sediment Trap observed a bathymetry crew.




15. MP26.25 Sediment Trap observed a bathymetry crew.



16. MP33.0A Sediment Trap observed a bathymetry crew.



17. MP33.0A Sediment Trap observed a bathymetry crew.



18. MP33.0B Sediment Trap observed a bathymetry crew.



19. Poling crew observed below Morrow Lake Dam.



20. Poling crew observed below Morrow Lake Dam.