

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, December 12, 2012

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	35.25	36.73
Ceresco Dam Control Point Boom	34.85	41.30
C3.2 Boat Launch Gauge	35.30	38.17
C5 Boat Launch Gauge	35.35	36.73
E4 Boat Launch Gauge	38.83	39.43




1. MP5.63 LDB ice observed forming above the railroad trestles.



2. MP5.63 LDB ice observed forming below the railroad trestles.



3. Ceresco Dam impoundment observed a bathymetry team.



4. Ceresco Dam impoundment observed a bathymetry team.



5. MP5.63 – MP5.70 RDB observed ice forming.



6. MP5.63 RDB sheen observed.



7. MP5.55 RDB observed ice forming above the railroad trestles.



8. Observed a crew decanting and sampling the CSDs.



9. Observed core logging.



10. MP12.5 LDB observed an RI crew.



11. MP15.25 South Mill Pond observed ice forming.



12. MP10.5 LDB Sediment Trap observed ice forming.



13. MP10.4 RDB Sediment Trap observed ice forming.



14. Morrow Lake observed a sweep boat operating.



15. MP21.5 Sediment trap observed a bathymetry team.



16. MP21.5 Sediment trap observed a bathymetry team.



17. MP19.25 Sediment trap observed a bathymetry team.



18. MP19.25 Sediment trap observed a bathymetry team.