

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, December 15, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	39.37	38.41
Ceresco Dam Control Point Boom	37.63	40.42
C3.2 Boat Launch Gauge	37.32	38.28
C5 Boat Launch Gauge	36.99	37.65
E4 Boat Launch Gauge	37.35	38.71



1. MP5.60 LDB ice observed.



2. MP5.63 – MP5.75 LDB no ice observed.



3. MP5.63 – MP5.75 RDB no ice observed.



4. Observed sample logging at the C3.2 Pole Barn.



5. MP15.25 South Mill Pond area where sheen and tar globs were observed.



6. MP15.25 RDB sheen and tar globs observed



7. MP15.25 RDB sheen and tar globs observed.



8. MP15.25 RDB sheen and tar globs observed.



9. MP36.50 RDB no sheen observed.



10. Morrow Lake Delta observed a bathymetry team at former E4 Boom A location.




11. Morrow Lake Delta observed a bathymetry team at former E4 Boom A location.



12. Morrow Lake Delta observed sheen generated by bathymetry crew boat.



13. Morrow Lake Delta observed a bathymetry team at MP37.75 Island sediment trap.



14. Morrow Lake no ice observed.