

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, December 17, 2012


Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	42.25	43.36
Ceresco Dam Control Point Boom	41.59	41.93
C3.2 Boat Launch Gauge	41.59	42.51
C5 Boat Launch Gauge	41.70	41.43
E0.5 Boat Launch Gauge	42.36	42.98
E4 Boat Launch Gauge	42.35	42.45



1. MP5.15 – MP5.60 LDB area where sheen and tar globs were observed.
Sweep boat requested.



2. MP5.15 – MP5.60 LDB sheen and tar globs observed.



3. MP5.15 – MP5.60 LDB sheen and tar globs observed.



4. MP5.15 – MP5.60 LDB sheen and tar globs observed.



5. MP5.63 – MP5.80 LDB area where sheen and tar globs were observed.
Sweep boat requested.



6. MP5.63 – MP5.80 LDB sheen and tar globs observed.



7. MP5.63 – MP5.80 LDB sheen and tar globs observed.



8. Ceresco Dam control point boom observed sheen and tar globs collecting along boom. Sweep boat requested.



9. Ceresco Dam control point boom sheen and tar globs observed.



10. Ceresco Dam control point boom sheen and tar globs observed.



11. Ceresco Dam control point boom sheen and tar globs observed.



12. MP5.63 – MP5.65 RDB sheen and tar globs observed. Sweep boat requested.



13. MP5.63 – MP5.65 RDB sheen and tar globs observed.



14. MP5.63 – MP5.65 RDB sheen and tar globs observed.



15. MP5.63 – MP5.65 RDB sheen and tar globs observed.



16. MP5.63 – MP5.65 sheen and tar globs observed.



17. MP5.50 – MP5.60 RDB area where sheen and tar globs observed. Sweep boat requested.



18. MP5.50 – MP5.60 RDB sheen and tar globs observed.



19. MP 5.50 – MP5.60 RDB sheen and tar globs observed.



20. MP5.50 – MP5.60 RDB sheen and tar globs observed.



21. Observed core logging and sampling at the C3.2 Pole Barn.




22. MP12.75 LDB observed the RI crew collecting soil cores.



23. MP14.75 – MP15.00 RDB sheen and tar globs observed.



24. MP14.75 – MP15.00 RDB sheen and tar globs observed.



25. MP14.75 – MP15.00 RDB sheen and tar globs observed.



26. MP15.25 South Mill Pond sheen and tar globs observed.



27. MP15.25 South Mill Pond sheen and tar globs observed.




28. MP15.25 South Mill Pond sheen and tar globs observed.



29. MP21.50 Oxbox observed a team completing bathymetry work at location.



30. Morrow Lake Delta observed a bathymetry team at MP37.75 sediment trap.



31. Morrow Lake Delta observed a bathymetry team at former E4 Boom D location.



32. Morrow Lake Delta observed a bathymetry team at former E4 Boom A location.



33. Morrow Lake Delta observed a bathymetry team at Delta A.



34. MP36.25 LDB area where Situation Unit performed a sheen test.



35. MP36.25 LDB sheen test conducted, results were inconclusive.



36. Morrow Lake North Cove area where sheen and tar globs were observed. Sweep boat requested.



37. Morrow Lake North Cove sheen and tar globs observed.



38. Morrow Lake North Cove sheen and tar globs observed.



39. Morrow Lake South Cove sheen and tar globs observed. Sweep boat requested.



40. Morrow Lake South Cove sheen and tar globs observed.