

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, December 20, 2012

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	42.30	43.42
E0.5 Boat Launch Gauge	44.25	45.33
E4 Boat Launch Gauge	40.73	41.09



1. Water gauge at C0.4 boat launch. No sheen or ice observed in inclement weather conditions.



2. MP 5.63 RDB, bathymetry crews return to Ceresco Dam to re-survey some bathymetry points.



3. C0.4 boat launch. Containment crews observed removing control point boom from Ceresco Dam. Boom placed in roll-off box for disposal.



4. Ceresco Dam following removal of control point boom above dam.



5. MP 15.50 South Mill Pond, no sheen or ice observed.



6. MP 15.5 North Mill Pond, no sheen or ice observed.



7. Bathymetry crews working in morning in Morrow Lake Delta. Work was shut down mid-day due to high winds and heavy rain.



8. Bathymetry crews on shore in Morrow Lake Delta.