

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, December 22, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	36.77	39.64
C3.2 Boat Launch Gauge	37.63	39.91
MP 21.5 RDB Gauge	38.06	39.92
E4 Boat Launch Gauge	38.23	38.54



1. MP 5.25 LDB, no ice observed along river bank.



2. MP 5.63 LDB, no ice observed along river bank.



3. Ceresco Dam, no ice observed.



4. Ceresco Dam, no ice observed.



5. MP 15.50 South Mill Pond, no ice observed.



6. MP 15.5 North Mill Pond, no ice observed.



7. MP 21.5 RDB Sediment Trap, no ice observed forming in backchannel.



8. MP 36.5 RDB, no ice observed forming in backwater.



9. Morrow Lake North Cove, no ice observed.



10. Morrow Lake South Cove, no ice observed.