

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, January 22, 2013

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Source Area, observed frozen over.



2. Frac Tank City, no decon operations observed.



3. MP2.75 Observed the start of the river beginning to freeze over.



4. MP3.25 Observed the river close to completely frozen over.



5. Ceresco Dam impoundment, observed the impoundment close to completely frozen over.



6. Ceresco Dam impoundment, observed the impoundment close to completely frozen over.



7. MP10.4 Sediment Trap ice conditions.



8. MP10.5 Sediment Trap ice conditions.



9. MP10.75 Sediment Trap ice conditions.



10. MP11.5 Observed the river close to completely frozen over.



11. MP14.75 Sediment Trap ice conditions.



12. Observed the Mill Ponds ice conditions.



13. MP19.25 Sediment Trap ice conditions.



14. MP19.25 Sediment Trap ice conditions.



15. MP20.75 RDB observed the RI Crew.



16. MP21.5 Sediment Trap ice conditions.



17. MP23.5 Observed two trees across the river.



18. MP26.0 Sediment Trap ice conditions.



19. MP28.25 Sediment Trap ice conditions.



20. MP30.8 Sediment Trap ice conditions.



21. MP33.0A Sediment Trap ice conditions.



22. MP33.0B Sediment Trap ice conditions.



23. MP36.10 Sediment Trap ice conditions.



24. MP36.5 Entering into the Morrow Lake Delta ice conditions.



25. Morrow Lake Delta ice conditions.



26. Morrow Lake Delta ice conditions.



27. Morrow Lake Neck and Morrow Lake Ice conditions.



28. Morrow Lake ice conditions.



29. What appears to be a buoy from Rowe Island observed midway along the south shoreline of Morrow Lake.



30. Morrow Lake ice conditions.