

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, January 26, 2013

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	N/A*	N/A*
E4 Water Gauge	N/A*	N/A*

* Water / Sediment Temperatures were unable to be collected due to ice formation along the river bank.

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. C0.4 Boat launch observed upstream river icing conditions.



2. C0.4 Boat launch observed downstream river icing conditions.



3. Ceresco Dam impoundment observed river icing conditions.



4. Ceresco Dam impoundment observed river icing conditions.



5. Ceresco Dam impoundment observed river icing conditions.



6. MP9.75 Downstream from Waddles Bridge observed river conditions.



7. MP9.75 Upstream from Waddles Bridge observed river conditions.



8. C3.2 Boat launch observed river icing conditions. River levels appeared to be dropping.



9. C3.2 Boat launch observed river icing conditions. River levels appeared to be dropping



10. MP15.25 South Mill Pond observed river icing conditions.



11. MP15.25 South Mill Pond observed river icing conditions.



12. MP15.5 North Mill Pond observed river icing conditions.



13. MP21.5 Oxbow observed river icing conditions.



14. MP21.5 observed river icing conditions.



15. E2 Boat launch observed river icing conditions. River levels appeared to be dropping.



16. MP27.0 E0.5 Boat launch observed river icing conditions.



17. MP27.0 E0.5 Boat launch observed river icing conditions.



18. Morrow Lake observed icing conditions.



19. Morrow Lake Neck/Morrow Lake Delta observed icing conditions.



20. Morrow Lake Delta observed icing conditions.



21. Morrow Lake Delta observed icing conditions.



22. Morrow Lake Delta observed icing conditions.