

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Monday, January 28, 2013

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	N/A*	N/A*
E4 Water Gauge	N/A*	N/A*

\* Water / Sediment Temperatures were unable to be collected due to ice formation along the river bank.



1. MP2.00 the confluence observed upstream river ice conditions.



2. Saylor's Landing Boat Launch observed downstream river ice conditions.



3. C0.4 Boat Launch observed upstream river ice conditions.



4. C0.4 Boat Launch observed downstream river ice conditions.



5. Ceresco Dam impoundment observed river ice conditions.



6. Ceresco Dam impoundment observed river ice conditions.



7. Ceresco Dam impoundment observed river ice conditions.



8. MP7.25 observed downstream river ice conditions.



9. C3.2 Pole Barn observed core logging operations.



10. C3.2 Boat Launch observed upstream river ice conditions. River level appeared to have dropped.



**11. C3.2 Boat Launch observed downstream river ice conditions. River level appeared to have dropped.**



**12. MP15.25 South Mill Pond observed river ice conditions.**



13. MP15.25 South Mill Pond observed back water ice conditions.



14. MP15.50 North Mill Pond observed river ice conditions.



**15. MP15.50 North Mill Pond observed back water ice conditions.**



**16. MP21.50 observed upstream river ice conditions.**



17. MP21.50 observed downstream river ice conditions.



18. MP21.50 Oxbow observed river ice conditions.



19. MP27.50 Shady Bend Campground observed river ice conditions.



20. E2 Boat Launch observed river ice conditions. River level appeared to have dropped.



21. Morrow Lake Delta observed ice conditions.



22. Morrow Lake Delta observed ice conditions.



23. Morrow Lake Neck/Morrow Lake Delta observed ice conditions.



24. Morrow Lake observed ice conditions.



25. C3.2 Pole Barn observed ultraviolet assessment on hexane sheen tests.



26. C3.2 Pole Barn ultraviolet assessment on hexane sheen tests.