

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, January 29, 2013

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	35.64	38.88
E4 Water Gauge	N/A*	N/A*

* Water / Sediment Temperatures were unable to be collected due to ice formation along the river bank.



1. C0.4 Boat Launch upstream, ice has receded from river channel.



2. C0.4 Boat Launch downstream, ice has receded from river channel.



3. Ceresco Dam impoundment observed river ice conditions.



4. Ceresco Dam impoundment observed river ice conditions.



5. C3.2 Boat Launch ice has receded from river channel.



6. C3.2 Pole Barn observed core logging procedures.



7. MP11.75 observed river ice conditions.



8. MP11.78 Sediment Trap observed ice conditions.



9. MP15.25 South Mill Pond observed river ice conditions.



10. MP15.25 South Mill Pond observed back water ice conditions.



11. MP15.50 North Mill Pond observed river ice conditions.



12. MP15.50 North Mill Pond observed back water ice conditions.



13. MP20.50 LDB observed the RI team.



14. MP21.50 Oxbow ice has receded from back channel.



15. MP21.50 ice has receded from river channel.



16. MP27.00 Shady Bend Campground ice has receded from upstream river channel.



17. MP27.00 Shady Bend Campground observed downstream ice conditions.



18. E2 Boat Launch ice has receded from river channel.



19. Morrow Lake Delta observed ice conditions.



20. Morrow Lake Delta observed ice conditions.



21. Morrow Lake Delta observed ice conditions.



22. Morrow Lake Neck/Morrow Lake Delta observed ice conditions.



23. Morrow Lake observed ice conditions.