

US EPA ARCHIVE DOCUMENT



Situation Update


January 30, 2013

Submerged Oil Science

UV Assessment of hexane sheen tests
01.28.2013




- 7 Tests Evaluated
- 3 Tests were positive for UV Florescence
- UV Florescence observed from tests at MP 6.60 RDB, MP 36.30 LDB, and MP 36.5 RDB



River Icing Conditions

Ceresco Dam Impoundment


01.23.2013



River Icing Conditions

Ceresco Dam Impoundment


01.24.2013



River Icing Conditions

Ceresco Dam Impoundment

01.28.2013



River Icing Conditions


C3.2 Boat Launch
01.23.2013



River Icing Conditions

C3.2 Boat Launch

01.26.2013



River Icing Conditions

C3.2 Boat Launch


01.29.2013



River Icing Conditions

MP 10.35 LDB


01.23.2013



River Icing Conditions

South Mill Pond – MP 15.25


01.23.2013



River Icing Conditions

South Mill Pond – MP 15.25


01.28.2013



River Icing Conditions

North Mill Pond – MP 15.5


01.24.2013



River Icing Conditions

North Mill Pond – MP 15.5


01.29.2013



River Icing Conditions

MP 21.5 Oxbow

01.23.2013



River Icing Conditions

MP 21.5 Oxbow

01.28.2013



River Icing Conditions

MP 21.5 Oxbow

01.29.2013



River Icing Conditions

Morrow Lake Delta

01.23.2013



River Icing Conditions

Morrow Lake Delta

01.26.2013



River Icing Conditions

Morrow Lake Delta

01.28.2013



River Icing Conditions

Morrow Lake

01.24.2013



River Icing Conditions

Morrow Lake

01.28.2013

