

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, January 31, 2013

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:
Karen Berez
START-USEPA
Situation Unit Leader



1. Source Area, observed frozen over.



2. Frac Tank City observed Cells A/B cleared and grading/berm work.



3. MP3.75 observed increased river level conditions.



4. Ceresco Dam impoundment observed elevated river level.



5. Ceresco Dam impoundment observed elevated river level along RDB.



6. Ceresco Dam observed greater river flow over spillway.



7. MP10.35 LDB observed increased river level conditions.



8. MP10.5 Sediment Trap ice conditions.



9. MP10.75 Sediment Trap observed increased river level conditions.



10. MP11.25 observed elevated river level conditions.



11. MP11.78 Sediment trap observed increased river level conditions.



12. MP11.78 Sediment Trap observed increased river level conditions.



13. MP14.75 Sediment Trap observed increased river level conditions.




14. Observed elevated river level at the Mill Ponds.



15. MP17.25 RDB observed the RI Crew.



16. MP19.25 Sediment Trap observed increased river level conditions.



17. MP21.5 Sediment Trap observed increased river level conditions.



18. MP26.0 Sediment Trap observed increased river level conditions.



19. MP27.00 Shady Bend Campground observed increased river level conditions.



20. MP27.00 Shady Bend Campground observed elevated river level conditions.



21. MP27.00 Shady Bend Campground observed elevated river level conditions.



22. E2 Boat Launch observed elevated river level conditions.



23. MP36.50 observed river conditions entering Morrow Lake Delta.



24. Morrow Lake Delta no ice observed.



25. Morrow Lake Neck/Morrow Lake Delta observed slight increase in lake level.



26. Morrow Lake observed slight increase in lake level.