

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Thursday, February 7, 2013

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	N/A*	N/A*
E4 Water Gauge	N/A*	N/A*

\*Water/Sediment Temperatures were unable to be collected due to ice formation along the river bank.

Prepared by:  
Karen Berecz  
START-USEPA  
Situation Unit



1. MP2.00 Confluence observed ice conditions.



2. MP2.25 Saylor's Landing observed river ice conditions.



3. C0.4 Boat Launch observed river ice conditions.



4. C0.4 Boat Launch observed river ice conditions.



5. Ceresco Dam impoundment observed river ice conditions.



6. Ceresco Dam impoundment observed river ice conditions.



7. C3.2 Pole Barn observed core logging procedures.



8. C3.2 Boat Launch observed river ice conditions.



9. MP15.00 RDB observed RI team



10. MP15.25 South Mill Pond observed river ice conditions.



11. MP15.25 South Mill Pond observed back water ice conditions.



12. MP15.50 North Mill Pond observed river ice conditions.



13. MP15.50 North Mill Pond observed back water ice conditions.



14. MP21.50 Oxbow observed ice conditions.



15. MP21.50 RDB sheen observed.



16. MP21.50 observed river ice conditions.



**17. MP27.00 Shady Bend Campground observed upstream river ice conditions.**



**18. MP27.00 Shady Bend Campground observed downstream river ice conditions.**



19. E2 Boat Launch observed upstream river ice conditions.



20. E2 Boat Launch observed downstream river ice conditions.



21. Morrow Lake Delta observed ice conditions.



22. Morrow Lake Delta observed ice conditions.



**23. Morrow Lake Neck/Morrow Lake Delta observed ice conditions.**



**24. Morrow Lake observed ice conditions.**