

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/12/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
09:45	<ul style="list-style-type: none"> • C0.4 Boat launch met up with Enbridge counterpart. • C0.4 Boat launch observed river icing conditions. • MP5.75 RDB observed sheen and tar globs. • MP5.70 RDB observed sheen and tar globs. • Ceresco Dam Impoundment observed river icing conditions. • MP5.89 RDB above Ceresco Dam observed sheen. • Ceresco Dam CSD Sampling Device from the RDB above the dam observed below the dam. • C3.2 Pole Barn observed core logging operations. • C3.2 Boat Launch observed river icing conditions. • MP15.25 South Mill Pond observed river icing conditions. • MP15.25 South Mill Pond observed sheen frozen in the ice. • MP15.25 South Mill Pond observed sheen and tar globs frozen in the ice. • MP15.75 North Mill Pond river icing conditions. • MP15.75 RDB observed sheen and tar globs frozen in the ice. • MP21.5 Observed river icing conditions. • D2 Boat Launch observed river icing conditions. • E0.5 Boat Launch Shady Bend Campground observed river icing conditions. • Morrow Lake observed icing conditions. • Morrow Lake Neck /Morrow Lake Delta River icing conditions. • Morrow Lake Delta river icing conditions. • MP36.5 35th Street Bridge RDB observed sheen. • Morrow Lake Delta icing conditions. • MP21.40 LDB observed the RI crew. • MP21.4 LDB observed tar glob and sheen. • MP21.4 LDB observed tar glob and sheen. • MP19.25 Sediment Trap observed CSD buoy moved. 			

1400	Returned to ICP.
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START	