

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/16/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
09:30	<ul style="list-style-type: none"> • Arrived at C0.4 boat launch and joined my Enbridge counterpart. • C0.4 Boat launch river conditions observed. No sheet ice was observed within the river. • Ceresco Dam impoundment river conditions observed. No sheet ice was observed within the river. • MP5.89 Ceresco Dam river icing conditions observed. Minimal bank ice was observed. • C3.2 Boat launch river conditions observed. No sheet ice was observed within the river. • MP15.25 South Mill Pond river icing conditions observed. Ice was observed within the stagnate portions of the mill pond. • MP15.25 river conditions observed. No sheet ice was observed within the river. • MP21.5 Sediment Trap river conditions observed. No sheet ice was observed within the river. • MP21.5 river conditions observed. No sheet ice was observed within the river. • MP27.0 Shady Bend Campground river conditions observed. No sheet ice was observed within the river. • E2 Boat launch river conditions observed. No sheet ice was observed within the river. • Morrow Lake icing conditions observed. Ice cover was observed west of the islands. • Morrow Lake Delta Neck river icing conditions observed. No sheet ice was observed within the river. • Morrow Lake Delta river conditions. No sheet ice was observed within the river. • Buoys from Rowe Island previously observed during an overflight were located and removed. Buoys were removed on Friday February 15, 2013. 			
1600	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				