

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, February 16, 2013

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	35.01	38.64
C3.2 Water Gauge	34.62	38.17
E0.5 Water Gauge	35.00	37.05
E2 Boat Launch	34.89	41.15
E4 Boat Launch	35.80	36.35

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. C0.4 Boat launch river conditions observed.



2. C0.4 Boat launch river conditions observed.



3. Ceresco Dam impoundment river conditions observed.



4. MP5.89 Ceresco Dam river icing conditions observed.



5. C3.2 Boat launch river conditions observed.



6. MP15.25 South Mill Pond river icing conditions observed.



7. MP15.25 river conditions observed.



8. MP21.5 Sediment Trap river conditions observed.



9. MP21.5 river conditions observed.



10. MP27.0 Shady Bend Campground river conditions observed.



11. E2 Boat launch river conditions observed.



12. Morrow Lake icing conditions observed.



13. Morrow Lake Delta Neck river icing conditions observed.



14. Morrow Lake Delta river conditions.



15. Morrow Lake Delta river conditions.



16. Buoys from Rowe Island previously observed during an overflight were located and removed.

Photograph Taken Friday February 15, 2013



17. Buoys from Rowe Island previously observed during an overflight were located and removed.