

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Monday, February 18, 2013

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	32.90	34.71
C3.2 Water Gauge	32.66	35.79
E0.5 Water Gauge	33.23	36.61
E2 Boat Launch	33.30	39.39
E4 Boat Launch	N/A*	N/A*

\*Water/Sediment Temperatures were unable to be collected due to ice formation along the river bank.



1. C0.4 Boat launch river conditions observed in the morning.



2. C0.4 Boat launch river conditions observed in the afternoon.



3. C0.4 Boat Launch seen observed within the ice.




4. MP5.75 RDB seen observed within a pool of melted ice.




5. MP5.75 Ceresco Dam impoundment river icing conditions observed in the morning.



6. MP5.75 Ceresco Dam impoundment river icing conditions observed in the afternoon.



7. C3.2 Pole Barn observed core logging.



8. C3.2 Pole Barn observed core logging.



9. C3.2 Observed river icing conditions.



10. MP15.25 South Mill Pond observed river icing conditions.



11. MP21.5 Sediment trap observed river icing conditions.



12. MP27.0 Shady Bend Campground observed river conditions.



13. MP26.0 Sediment trap observed the CSD sampling crew.



14. E2 Boat launch observed river conditions.



15. MP28.5 RDB observed the RI crew.



16. Morrow Lake Delta icing conditions observed.



17. Morrow Lake Delta icing conditions observed.



18. Morrow Lake icing conditions observed.



19. Morrow Lake Delta Neck icing conditions observed.



20. Morrow Lake E4 boat launch icing conditions observed.