

US ERA ARCHIVE DOCUMENT


C. Intervenor's exhibit 214 (referenced in Chapter 2) from *Petitions Of The Keweenaw Bay Indian Community, et al. On Permits Issued To Kennecott Eagle Minerals Company* (Michigan Department of Environmental Quality)


ATTORNEY/CLIENT PRIVILEGE






ATTORNEY/CLIENT PRIVILEGE






ATTORNEY/CLIENT PRIVILEGE



Below is a drill hole trace map with the above holes on Level 275.



Drill Hole Plan showing holes 20, 47, 54, 73, 77, 83, 84 and 107

As per Dr. Pope's 275 level map, the drill holes shown above intercept what are possible water conductive features.

		ž.
		: