

SITE PHOTOGRAPHS
REMEDIAL ACTION FOR OPERABLE UNIT 1
GROUND WATER AND SURFACE WATER
TAR CREEK SUPERFUND SITE, OTTAWA COUNTY, OKLAHOMA



Roof Collapse Into the Mine Workings in Kansas - The arrow points to the top of the dike designed to direct the flow of Tar Creek away from the collapse structure.



Acid Mine Drainage - The acid mine water is draining into Tar Creek at Douthat Bridge (approximately 1.5 miles southeast of Cardin, OK). Note the reddish iron oxide staining on the vegetation and banks of the creek.