

US EPA ARCHIVE DOCUMENT



Guam Waterworks Authority (VP0989)

SDWA Sanitary Survey

Tumon, Guam

Southern System

NEIC Field Investigation Photographs

April 26 and May 2, 2012



Overview Map



US EPA ARCHIVE DOCUMENT

File Name: RIMG0074.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/26/2012 1:20:36 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Overview of Brigade pump station



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 1:26:14 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Leaking gate valve on discharge line

File Name: RIMG0076.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██
Elevation	██
Date Time Stamp	4/26/2012 1:27:08 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Hole in floor with electrical exposure



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 1:27:23 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Leaking discharge line where it exits station



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 1:30:23 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Air relief assembly



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	██████
Date Time Stamp	4/26/2012 1:30:44 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Close-up air relief valve

File Name: RIMG0080.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 1:34:00 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Bypass pipe exiting pump station which discharges to ground (right). Floor drain that discharges to ground (left).



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 1:35:17 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	Close-up of floor drain that discharges to ground

File Name: RIMG0082.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████████
Date Time Stamp	4/26/2012 1:36:30 PM
Photographer	K. Sable
Comment	Brigade Pump Station
Description	2 " x 4 " board supporting pipe

File Name: RIMG0083.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████████
Date Time Stamp	4/26/2012 1:57:18 PM
Photographer	K. Sable
Comment	Windward Hills Tank
Description	Overview of tank

File Name: RIMG0084.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████ /
Elevation	██████
Date Time Stamp	4/26/2012 1:58:51 PM
Photographer	K. Sable
Comment	Windward Hills Tank
Description	Rust on tank



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:00:24 PM
Photographer	K. Sable
Comment	Windward Hills Tank
Description	Ladder



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:07:10 PM
Photographer	K. Sable
Comment	Windward Hills Tank
Description	Overflow pipe with vegetation

File Name: RIMG0087.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	██████
Date Time Stamp	4/26/2012 2:21:45 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Pump station building



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:26:49 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Sample tap

File Name: RIMG0089.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/26/2012 2:27:16 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	No bolts on pump # 1



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/26/2012 2:27:59 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Pump # 1 open to running parts



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:29:02 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Pump # 2 wasp nests and corrosion

File Name: RIMG0092.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/26/2012 2:29:30 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Ceiling paint corrosion



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:29:53 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Pump # 3 leak and corrosion

File Name: RIMG0094.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/26/2012 2:31:30 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Outside hose pulled through window

File Name: RIMG0095.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 2:33:11 PM
Photographer	K. Sable
Comment	Windward Hills Pump Station
Description	Stockpile of debris outside pump station

File Name: RIMG0096.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/26/2012 2:59:48 PM
Photographer	K. Sable
Comment	Sinifa Tank
Description	Overview of tank



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 3:02:27 PM
Photographer	K. Sable
Comment	Sinifa Tank
Description	Access ladder


File Name: RIMG0098.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 3:05:06 PM
Photographer	K. Sable
Comment	Sinifa Tank
Description	Pitting on side of tank

File Name: RIMG0099.JPG



Attributes


Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/26/2012 3:06:38 PM
Photographer	K. Sable
Comment	Sinifa Tank
Description	Moss clumps on side of tank

File Name: RIMG0100.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/26/2012 3:07:40 PM
Photographer	K. Sable
Comment	Sinifa Tank
Description	Moss clump close-up



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 2:13:31 PM
Photographer	K. Sable
Comment	Agate # 1 Pump Station
Description	Sign for vandals posted inside pump station

File Name: RIMG0218.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
[REDACTED]	[REDACTED] 2:56:34 PM
Photographer	D. Parker
Comment	Umatac Tank
Description	Cooler with rotting food adjacent to tank

File Name: RIMG0219.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 2:57:09 PM
Photographer	K. Sable
Comment	Umatac Tank
Description	Overview of tank

File Name: RIMG0220.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	5/2/2012 3:08:01 PM
Photographer	K. Sable
Comment	Umatac # 2 Pump Station
Description	Overview

File Name: RIMG0221.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	5/2/2012 3:39:44 PM
Photographer	K. Sable
Comment	Pigua Tank
Description	Inlet and outlet box



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 3:40:07 PM
Photographer	K. Sable
Comment	Pigua Tank
Description	Overview of tank

File Name: RIMG0223.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	████
Elevation	████
Date Time Stamp	5/2/2012 3:50:40 PM
Photographer	K. Sable
Comment	Pigua Pump Station
Description	Overview

File Name: RIMG0224.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	5/2/2012 4:04:52 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Overview

File Name: RIMG0225.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	5/2/2012 4:05:14 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Overview



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 4:07:06 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Broken line # 3

File Name: RIMG0227.JPG



Attributes

Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	5/2/2012 4:07:30 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Broken line # 3 facing other direction

File Name: RIMG0228.JPG



Attributes

Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██
Elevation	██
Date Time Stamp	5/2/2012 4:07:51 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Overview



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	5/2/2012 4:08:11 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Pump and line # 1

File Name: RIMG0230.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	5/2/2012 4:08:33 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Overview

File Name: RIMG0231.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 4:09:04 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Line # 2 and line # 3



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	5/2/2012 4:17:57 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Palm tree growing into wall

File Name: RIMG0233.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	Southern System
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	5/2/2012 4:21:16 PM
Photographer	K. Sable
Comment	Geus Pump Station
Description	Overview