UNIT LOG	1. Incident Name	2. Date Prepared	3. Time Prepared
	Kalamazoo River/Enbridge Oil Spill	10/20/2012	1745
4. Unit Name/Designators	5. Unit Leader (Name and Position)		6. Operational Period
Situation Unit	Mindy Luetke, Planning Section Chief		0800, 10/20/12 – 1400, 10/20/12

7. Personnel Roster Assigned		
Name	ICS Position	Home Base
Karen Berecz	Situation Unit 1	Dallas, TX

8. Activity Log	
Time	Major Events

	Situation Unit Observations:
0730	· Attend daily safety meeting at C3.2.
0800	· Arrive at E4 Boat Launch. Depart on boat. · E4 water level gauge: 0.90; Water Temp: 52.46^{0}F; Sediment Temp: 53.54^{0}F · South Cove: Very random blobs of silver oil sheen observed free floating along south and east shoreline. Area of impact 25'x1'. Quantity of sheen observed did not warrant sweep boat. · North Cove: Very random blobs of silver oil sheen observed free floating along west shoreline. Area of impact 10'x2'. Quantity of sheen observed did not warrant sweep boat. · Morrow Lake (Main channel, North Shoreline, Rowe Island and Little Island): No oil and/or oil sheen observed at locations. · Morrow Lake Delta Gate C West: Small streamers of silver oil sheen observed along boom. · Morrow Lake Delta Gate E South: No oil and/or oil sheen observed along boom. · Morrow Lake Delta Gate F South: Very small, random blobs of silver oil sheen observed along boom. · 35th Street Bridge: Water level reading on gauge is 0.30 above baseline of 0. · MP36.25 - MP36.50: Streamers of silver oil sheen intermixed with sediment observed swirling along LDB of MP36.25. Area of impact 10'x5'. Quantity of sheen observed did not warrant sweep boat.
1025	· Arrive at Custer Road Bridge, MP21.50, perform observation of location from bridge spanning river. Sweep boat observed performing sheen management at location. No oil and/or oil sheen observed.
1100	· Arrive at C5 Boat Launch. Depart on boat. · Water temp: 52.88^{0}F; Sediment temp: 53.88^{0}F. · MP15.00 – MP15.65: No oil and/or oil sheen observed along river segment or at South and North Mill Ponds. · Arrive at C3.2 Boat Launch. Depart on boat. · C3.2 water level gauge: 1.90; Water Temp: 53.33^{0}F; Sediment Temp: 54.17^{0}F · MP8.50 L1: One small streamer of silver oil sheen observed at location. Quantity of sheen observed too insignificant to quantify. · MP8.50 L3: No oil and/or oil sheen observe at location. · MP8.75 R1: No oil and/or oil sheen observed at location. · MP10.75 LDB: No oil and/or oils sheen observe on backchannel.
1500	· Arrive at C0.4 Boat Launch. Depart on boat. · C0.4 Water Level Gauge: 1.75; Water Temp: 54.745^{0}F; Sediment Temp: 55.395^{0}F. · MP5.25 – MP5.60 LDB: Streamers and blobs of silver oil sheen along with occasional oil globules observed free floating along river segment. Area of impact 50' x 1'. Quantity of sheen observed did not warrant sweep boat. · MP5.63 – Control Point LDB: Streamers of silver oil sheen along with an occasional oil globule observed free floating along river segment. Area of impact 25' x 5'. Verbally inform sweep boat crew to perform sheen management at location. · Control Point (MP5.65): Streamers of silver oil sheen along with occasional oil globule observed free floating along control point boom. Area of impact 75' x 1'. Quantity of sheen observed did not warrant sweep boat. · MP5.63 – CP RDB: Very random streamers of silver oil sheen observed free floating along river segment. Area of impact 10'x1'. Quantity of sheen observed did not warrant sweep boat.
1700	· MP 5.50 – MP5.60 RDB: No oil and/or oil sheen observed along river segment. · Arrive at ICP. End of field day.

9.	Prepared by (Name and Position) Karen Berecz, Situation Unit, USEPA-START