US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, December 5, 2012
Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	47.22	47.12
Ceresco Dam Control Point	45.06	47.11

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader

1. Source Area observed the pipeline installation preparation work continuing at the source area and across Talmadge Creek.

2. Frac Tank City, crews observed performing decon operations

US EPA ARCHIVE DOCUMENT



3. Ceresco Dam observed a bathymetry crew.

4. Ceresco Dam observed a bathymetry crew.

US EPA ARCHIVE DOCUMENT

5. MP4.5 LDB observed sheen and tar globs.

6. MP5.63 LDB observed sheen and tar globs. Sweep boat requested.

US EPA ARCHIVE DOCUMENT

7. Ceresco Dam control point boom observed sheen and tar globs collecting along the boom.

8. Ceresco Dam CSD removed during the bathymetry work.

US EPA ARCHIVE DOCUMENT

9. MP4.70 LDB observed sheen and tar globs.

10. MP10.4 RDB observed a bathymetry crew.

US EPA ARCHIVE DOCUMENT

11. MP10.75 LDB observed a bathymetry crew.

12. MP11.5 RDB observed an RI crew.

US EPA ARCHIVE DOCUMENT

13. MP15.5 South Mill Pond no sheen observed.

14. MP15.5 Utility work continues and new obstruction placed within the river.

US EPA ARCHIVE DOCUMENT

15. MP15.5 sheen observed within the boom around the trench box.

16. MP15.5 LDB observed sheen.

US EPA ARCHIVE DOCUMENT

17. MP26.0 RDB observed a bathymetry crew.

18. MP28.25 Oxbow observed sheen.

US EPA ARCHIVE DOCUMENT

19. MP30.8 Sediment Trap sheen observed in back channel.



20. MP30.8 Sediment Trap sheen observed in back channel.

US EPA ARCHIVE DOCUMENT



21. Morrow Lake observed the poling crew.

22. Morrow Lake observed the poling crew.

US EPA ARCHIVE DOCUMENT

23. MP37.75 RDB Sediment Trap observed sheen.

24. Morrow Lake Delta with the containment system removed.

US EPA ARCHIVE DOCUMENT