US EPA ARCHIVE DOCUMENT

US EPA ARCHIVE DOCUMENT

Inactive and Abandoned Uranium Mine Data Management

Navajo Uranium Stakeholders Workshop

Gallup, New Mexico

November 4, 2009

Susan Lucas Kamat, Geologist

New Mexico Mining & Minerals Division

New Mexico Energy, Minerals and Natural Resources Department

US EPA ARCHIVE DOCUMENT

Abandoned. Inactive Uranium Mines

Collapsed shaft

Subsidence

Waste piles

Open adits

US EPA ARCHIVE DOCUMENT

Inactive/Abandoned Uranium Mine Inventory



US EPA ARCHIVE DOCUMENT

Data Dictionary Implementation



US EPA ARCHIVE DOCUMENT

Calibrating Radiation Meters

US EPA ARCHIVE DOCUMENT

GPS-Linked Photos

US EPA ARCHIVE DOCUMENT

Field Data Stored in a Geospatial Database



US EPA ARCHIVE DOCUMENT

Data Sharing



- Limited resources require prioritizing abandoned uranium mine sites and leveraging resources across partners.
- Multi-agency involvement on federal, state and tribal levels with stakeholder consultation.
- Data sets that can easily be shared among partners.
- Data sets that other partners can use in their workflow.