

US EPA ARCHIVE DOCUMENT



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

December 14, 2009

OFFICE OF
SOLID WASTE AND
EMERGENCY RESPONSE

VIA E-MAIL AND FEDERAL EXPRESS

Mr. Michael Horvath
First Energy Generation Corporation
Bruce Mansfield Plant
P.O. Box 1281
Shippingport, Pa 15077-0128

Dear Mr. Horvath:

On September 1-2, 2009 the United States Environmental Protection Agency ("EPA") and its engineering contractors conducted a coal combustion residual (CCR) site assessment at the Bruce Mansfield facility. The purpose of this visit was to assess the structural stability of the impoundments or other similar management units that contain "wet" handled CCRs. We thank you and your staff for your cooperation during the site visit. Subsequent to the site visit, EPA sent you a copy of the draft report evaluating the structural stability of the units at the Bruce Mansfield facility and requested that you submit comments on the factual accuracy of the draft report to EPA. Your comments were considered in the preparation of the final report .

The final report for the Bruce Mansfield facility is enclosed. This report includes a specific rating for each CCR management unit and recommendations and actions that our engineering contractors believe should be undertaken to ensure the stability of the CCR impoundment(s) located at the Bruce Mansfield facility. These recommendations are listed in Enclosure 2.

Since these recommendations relate to actions which could affect the structural stability of the CCR management units and, therefore, protection of human health and the environment, EPA believes their implementation should receive the highest priority. Therefore, we request that you inform us on how you intend to address each of the recommendations found in the final report. Your response should include specific plans and schedules for implementing each of the recommendations. If you will not implement a recommendation, please explain why. Please provide a response to this request by January 15, 2010. Please send your response to:

Mr. Stephen Hoffman
US Environmental Protection Agency (5304P)
1200 Pennsylvania Avenue, NW
Washington, DC 20460

If you are using overnight or hand delivery mail, please use the following address:

Mr. Stephen Hoffman
US Environmental Protection Agency
Two Potomac Yard
2733 S. Crystal Drive
5th Floor, N-237
Arlington, VA 22202-2733

You may also provide a response by e-mail to hoffman.stephen@epa.gov

This request has been approved by the Office of Management and Budget under EPA ICR Number 2350.01.

You may assert a business confidentiality claim covering all or part of the information requested, in the manner described by 40 C. F. R. Part 2, Subpart B. Information covered by such a claim will be disclosed by EPA only to the extent and only by means of the procedures set forth in 40 C.F.R. Part 2, Subpart B. If no such claim accompanies the information when EPA receives it, the information may be made available to the public by EPA without further notice to you. If you wish EPA to treat any of your response as "confidential" you must so advise EPA when you submit your response.

EPA will be closely monitoring your progress in implementing the recommendations from these reports and could decide to take additional action if the circumstances warrant.

You should be aware that EPA will be posting the report for this facility on the Agency website shortly.

Given that the site visit related solely to structural stability of the management units, this report and its conclusions in no way relate to compliance with RCRA, CWA, or any other environmental law and are not intended to convey any position related to statutory or regulatory compliance.

If you have any questions concerning this matter, please contact Mr. Hoffman in the Office of Resource Conservation and Recovery at (703) 308-8413. Thank you for your continued ongoing efforts to ensure protection of human health and the environment.

Sincerely,
/Matt Hale/, Director
Office of Resource Conservation and Recovery

Enclosures

Enclosure 2
Bruce Mansfield Little Blue Run Recommendations

1. We recommend that the surface asphalt along the crest and downstream slopes of all embankments continue to be maintained as part of the plant facility's regular maintenance activities.
2. Clearing of vegetation, sealing of cracks, and repair of larger defects should be performed on a regular basis.
3. The hydrologic study for the site states that SDF will overtop the impoundments by approximately 0.3 foot. Passage of the SDF without erosion of the embankments is dependent on the asphalt layer, and it should not be allowed to degrade to a point where an overtopping could cause a failure.

Schedule: According to First Energy's current Maintenance Program.