

US EPA ARCHIVE DOCUMENT

<b>COMPANY</b>	Ohio Power Company
<b>PLANT</b>	Kammer
<b>ASH MANAGEMENT UNIT</b>	Boiler Slag Pond
<b>QUESTION 1</b>	
Dam Hazard Rating	
Who Established Rating	
Basis for Rating	
No Rating Assigned	X (Incised pond -- no dam or dike)
<b>QUESTION 2</b>	
Year Commissioned	1963
Year(s) Expanded	Modified 1968
<b>QUESTION 3 - Mark all that apply</b>	
Fly Ash	
Bottom Ash	
Boiler Slag	X
Flue Gas Emission Control Residuals	
Other (Specify)	
<b>QUESTION 4</b>	
Designed by P.E.	Not Available
Constructed under P.E. Supervision	Not Available
Inspection/monitoring under P.E. Supervision	No (No dam or dike)
<b>QUESTION 5</b>	
Date of Last Company Safety Assessment	Not Assessed (because it is an incised pond)
Describe Evaluator's Credentials	N/A
Describe Past Followup Corrective Actions	N/A
Describe Credentials of Corrective Action Implementers	N/A
Describe Planned Followup Actions	N/A
Date of Next Safety Assessment	N/A
<b>QUESTION 6</b>	
Date of Last Regulatory Safety Inspection	Not Inspected
Agency Name	N/A
Date of Planned Regulatory Safety Inspection	N/A
Agency Name	N/A
Copy of Most Recent Regulatory Inspection Included	N/A
<b>QUESTION 7</b>	
Safety Issues from Regulatory Inspections w/in Past Year	N/A
Corrective Actions	N/A
Documentation Included	N/A
<b>QUESTION 8</b>	
Surface Area (acres)	1.6 acres
Total Storage Capacity	22 acre-ft
Volume Currently Stored	Variable - ash is routinely removed for beneficial use
Date of Volume Measurement	N/A
Maximum Height (feet)	0
<b>QUESTION 9</b>	
Spills or Unpermitted Release History (10 Years)	No
<b>QUESTION 10</b>	
All legal owner(s) and operator(s)	Ohio Power Company