

US EPA ARCHIVE DOCUMENT

<b>COMPANY</b>	Columbus Southern Power Company
<b>PLANT</b>	Picway
<b>ASH MANAGEMENT UNIT</b>	Ash Pond
<b>QUESTION 1</b>	
Dam Hazard Rating	Low
Who Established Rating	Ohio DNR -- Div. of Water
Basis for Rating	Health Hazard
No Rating Assigned	N/A
<b>QUESTION 2</b>	
Year Commissioned	1954
Year(s) Expanded	Modification for closure -- 2008
<b>QUESTION 3 - Mark all that apply</b>	
Fly Ash	X
Bottom Ash	X
Boiler Slag	
Flue Gas Emission Control Residuals	
Other (Specify)	
<b>QUESTION 4</b>	
Designed by P.E.	Not Available (Columbus & Southern)
Constructed under P.E. Supervision	Not Available
Inspection/monitoring under P.E. Supervision	Yes
<b>QUESTION 5</b>	
Date of Last Company Safety Assessment	10/25/2007
Describe Evaluator's Credentials	OH P.E.
Describe Past Followup Corrective Actions	Routine maintenance
Describe Credentials of Corrective Action Implementers	Under plant supervision
Describe Planned Followup Actions	Regrade crest, toe, and portions of east and south embankments, routine maintenance
Date of Next Safety Assessment	2010
<b>QUESTION 6</b>	
Date of Last Regulatory Safety Inspection	2/9/2009
Agency Name	ODNR -- Div. of Water
Date of Planned Regulatory Safety Inspection	2011-2012
Agency Name	ODNR -- Div. of Water
Copy of Most Recent Regulatory Inspection Included	Yes (from 5/25/1995, 2009 rpt. not available)
<b>QUESTION 7</b>	
Safety Issues from Regulatory Inspections w/in Past Year	N/A
Corrective Actions	N/A
Documentation Included	N/A
<b>QUESTION 8</b>	
Surface Area (acres)	23 acres
Total Storage Capacity	275 acre-ft
Volume Currently Stored	Variable - ash is occasionally removed for beneficial use
Date of Volume Measurement	N/A
Maximum Height (feet)	24
<b>QUESTION 9</b>	
Spills or Unpermitted Release History (10 Years)	No
<b>QUESTION 10</b>	
All legal owner(s) and operator(s)	Columbus Southern Power Company