


US EPA ARCHIVE DOCUMENT



OTHER CONSIDERATIONS FOR BIOREACTOR OPERATIONS

- **Avoid use of metal valves and other fittings due to corrosive nature of off-gases and leachate**
- **Be prepared for the possibility of dealing with damage from field mice and other animals**
- **Loop header distribution system**
- **Strategic locating of shut-off valves along headers for isolation**



GEOTECHNICAL STABILITY

**EAST SLOPE
FEB 27, 2001**



GEOTECHNICAL STABILITY



SOUTH SLOPE – MAY 7, 2002

GEOTECHNICAL STABILITY



South Slope- May 2002

RESPONSE TO GEOTECHNICAL STABILITY ISSUES

- Continued monitoring of slope movement via sideslope risers
- All injection wells (air and leachate) located near top edge of slope have been shut off
- Rock buttresses built along south sideslope



Civil & Environmental Consultants, Inc.

Would like to thank the United States Environmental Protection Agency for the opportunity to present this research at the 2003 Workshop for Landfill Bioreactors

