

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/12/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/10/12 – 0700, 05/17/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • MP36.10, observed buoys deployed at the sediment trap location. • MP36.10, sheen observed in river channel. • MP36.5 RDB, sheen observed in river channel. • Morrow Lake Delta, observed poling crew. • Morrow Lake Delta, sheen observed around poling boats. • Morrow Lake Delta, sheen observed as sediment was disturbed by our boat. • Morrow Lake E4, buoys deployed. • Morrow Lake Delta, sheen observed between MP37.35 – MP37.75. • Morrow Lake north cove, sheen observed. 			
	Additional observations: None			
14:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				