

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/04/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/31/12 – 0700, 06/07/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Ceresco Dam, sheen observed between two booms. • MP7.25 Island, sheen and tar globs observed. • MP7.25 Island, sheen test performed. • MP10.75, sheen observed within boom. • MP11.25 R2 northwest corner of excavation, oil observed. • MP11.5, observed crew removing woody debris from river. • MP11.75, green boom has been replaced with yellow boom. • MP13.75, poling crew observed. • MP13.75 LDB, overbank pond poling observed . • MP13.75 LDB overbank pond, sheen observed. • MP13.75 LDB, overbank pond pump observed with spray nozzle. Pump utilized for decontamination of the ARGOS unit between locations. • MP13.75 LDB overbank pond, sheen observed. • MP14.65 LDB, poling crew observed. • MP14.98 I, sheen observed coming into island from Mill Pond channel. • MP15.25 Mill Ponds, sheen observed in river channel. • MP15.5 Mill Ponds, sheen observed in river channel. • Sweep boat observed responding to sheen in Mill Ponds river channel. • MP13.5, Poling crew observed. • MP13.25, Poling crew observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				