

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/07/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/07/12 – 0700, 06/14/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Source Area Pond, sheen observed around poling boat. • Source Area Pond northeast corner, sheen observed. • Source Area Pond, reassessment poling observed. • Ceresco Dam, crew observed performing boom maintenance. • Sheen observed after boat agitated sediment at Ceresco Dam. • Sediment plume observed after boat agitated sediment at Ceresco Dam. • Sheen observed going over Ceresco Dam. • Sheen observed at the Shady Bend boat launch. • MP26.75 RDB, sheen observed. • MP26.5, Poling crew observed. • MP26.25 RDB, sheen observed. • MP26.25 RDB, sweep boat responding. • MP26.0 RDB, sheen observed. • MP26.0 RDB, sheen observed after boat reversed. • MP30.8, sheen observed within boom. • MP30.8, Poling crew observed. • MP31.0, Poling crew observed. • MP34.25, Poling crew observed. • Morrow Lake, velocity measurements observed being taken. • Poling crew observed in the neck of the Delta and Lake. • Sheen observed in Morrow Lake Delta. • MP36.1, sheen observed within the river channel. • MP35.0, Poling crew observed. • MP34.25, Poling crew observed. • MP31.5, Poling crew observed. • MP15.75, Poling crew observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				