

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, June 8, 2012

Kalamazoo River / Enbridge Spill

Weather / River Conditions for Friday (6-08-2012)

Conditions: Sunny

Ambient Air Temperature High: 83° F

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Source area pond, sheen observed.



2. Source area pond, reassessment crew observed.



3. Source area pond, sheen observed.



4. Frac-Tank City, observed the timber mats being disposed of.



5. Island A sheen observed.



6. MP5.25 LDB sediment plume and sheen observed.



7. MP5.25 LDB sediment plume and sheen observed.



8. Ceresco Dam boom maintenance crew observed.



9. Ceresco Dam boom maintenance crew observed.



10. MP5.6 LDB sheen observed.



11. MP5.63 sheen observed.



12. MP10.75 Sediment trap.



13. MP11.25R1 sheen observed.



14. MP13.25 Poling crew.



15. MP13.25 Poling crew.



16. MP14.75 Sediment trap.



17. MP15.5 Mill Ponds sweep boat observed.



18. MP15.75 boom maintenance crew observed.




19. MP19.25 sediment trap sheen observed behind trap.



20. MP19.25 sediment trap.




21. MP23.0 RDB poling crew observed.



22. MP23.0 RDB poling crew observed.



23. MP26.25 back channel sheen observed.



24. MP28.25 oxbow sheen observed.



25. MP30.8 no sheen observed within the boom.



26. MP33.75 Poling crew observed.



27. MP33.75 Poling crew observed.



28. MP36.5 Poling crew observed.



29. Morrow Lake Delta Poling crew.



30. Morrow Lake Delta Poling crew.



31. Morrow Lake Delta Poling crew.



32. E4 sediment plume observed.



33. Morrow Lake north shoreline sweep boat observed.



34. Boom observed along south shoreline near the dam.