

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/13/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/07/12 – 0700, 06/14/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Observed containment crews removing boom from MP 8.5 L3 location. • North side of former excavation area at MP 11.25 R2 LDB: No sheen observed. • South side of former excavation area at MP 11.25 R2 LDB: No sheen observed. • Sediment trap at MP 10.75 LDB: Sheen observed within containment. • Sheen observed within containment at the MP 10.75 sediment trap. • Observed containment crew deploying a new sediment sampler on the downstream side of the MP 10.75 LDB sediment trap. • Observed sheen sweeper crew operating at the Mill Ponds just south of the Burnham Street Bridge. • Observed sheen observed in the river channel at the Mill Pond upstream from the Battle Creek Spillway control point. • Northern end of the Mill Pond looking west: No sheen observed. • Observed poling crew operating in overbank channel near MP 24.6 LDB. • Observed sheen generated and cleaned up by poling crews in overbank channel near MP 24.6 LDB. • Observed air monitoring crew collecting air samples near MP 27.00 LDB. • Observed shallow rocks and river hazards flagged by boat crews due to low river levels. • Observed poling crew and sheen sweep boat operating in southeastern portion of Morrow Lake Delta. • Observed poling crew and sweeper boat operating near southern shore of Morrow Lake Delta. • Observed containment crews removing debris from E 4.0 control point. • Sheen and tar globules observed along upstream side of E 4.0 control point. • Observed poling crew surveying in the southwestern corner of Morrow Lake Delta. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				