

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/16/2012	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/14/12 – 0700, 06/21/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Oxbow at MP21.5. Containment boom was removed from this location yesterday. • Sheen observed by Operations at 21.5 oxbow. Sweeper boat called to conduct sheen sweep at this location. • Poling crews deploying out of Shady Bend Campground at MP 27.0. • Sediment trap at 28.25: No activity observed. • Former boom location at 30.8: No sheen observed. • Poling crews observed working near MP 32.15 RDB. • Poling crew observed upstream from MP 36.1 sediment trap. • Poling crews observed conducting assessment near MP 32.0. • Poling crew observed on upstream side of E 4.0 Control Point. • Observed debris removal from E 4.0 Control Point. • EPA contractors and Enbridge contractors observed inspecting newly installed sediment curtain at E 4.0 Control Point. • Observed Enbridge contractor collecting river velocity measurements at MP 37.75 in the Morrow Lake neck. • Observed pontoon boat used to install the sediment curtain at E 4.0 parked at boat launch. Sediment curtain installation was completed yesterday. 			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				