

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/22/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/21/12 – 0700, 06/28/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Observed boom and curtain staged at the E4 boat launch.</li> <li>• Observed pipe staged at the E4 boat launch for anchoring boom.</li> <li>• Sheen observed at the E4 boat launch.</li> <li>• Observed the public utilizing Lake Morrow.</li> <li>• Morrow Lake: sheen observed southeast of Indian Island.</li> <li>• Morrow Lake: sheen and globs observed north of the small island E4.5 was anchored to.</li> <li>• Morrow Lake: observed crew installing anchoring pipe.</li> <li>• Morrow Lake Delta: temporary boom configuration.</li> <li>• Observed public fishing at the 35<sup>th</sup> Street Bridge.</li> <li>• MP30.8 LDB: sheen observed.</li> <li>• Observed public fishing at MP30.25.</li> <li>• MP23.15: observed sheen generated from boat agitation and tested.</li> </ul>			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				