

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/26/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/21/12 – 0700, 06/28/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Beedle Lake Bridge: USGS observed performing discharge measurements. • MP15.5 South Mill Pond north corner: observed sheen flowing out of Mill Pond into river. Operations notified and sweep boat was observed in the area. • Observed sheen sweep boat operating near C5 boat launch. • Observed sheen sweep boat operating near MP5.5 LDB. • MP37.75: Observed crews deploying boom. • MP37.75: Newly installed boom. • Observed crew installing curtain onto boom. • MP37.75: Newly installed booms. • MP37.75: Observed crews installing additional anchor point. • Observed sheen sweep boat operating in the north cove of Morrow Lake. • Morrow Lake poling crew observed. • Observed person kayaking into closed section of Morrow Lake Delta. • Observed sheen/glob samples being collected at MP30.8LDB. • Observed sheen/glob samples being collected at MP33.0 A. • Observed sheen/glob samples being collected at MP33.0 B. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				