

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/28/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • MP15.5 Mill Pond: sheen sweep observed. • MP15.5 South Mill Pond north corner: observed sheen flowing out of Mill Pond into river. Operations was notified and sweep boat was observed in the area. • Observed sheen sweep boat responsible for routine daily sweeps in MP21.5 – MP30 range. • MP21.5 Custer Drive bridge sheen observed. Operations was notified and sweep boat was deployed. • Morrow Lake Delta: observed USGS taking velocity measurements. • Morrow Lake Delta: observed poling crew. • MP37.5 Morrow Lake Delta sheen observed. Operations was notified and a sheen boat was deployed. • MP37.75 Newly installed booms. • MP37.75 Observed boom deployed near E4 control point. • Observed crew installing new anchor point for boom. • Morrow Lake Delta: observed crew removing former E4 control point boom. • Morrow Lake: sheen observed. • Morrow Lake: sheen sweep boat responding to sheen sighting. • Ceresco Dam: sheen observed. Operations was notified • Ceresco Dam: portage work continued. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				