

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/30/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Ceresco Dam: portage work continued below the dam. • Ceresco Dam: observed sheen sweep boat. • Ceresco Dam: sheen observed along the south side of the dam at the dam. Sweep boat restricted from accessing this area. • Observed sheen sweep boat operating around the railroad trestle. • Observed sheen around the railroad trestle. Sheen sweep boat operating in the area. • MP14.75: Sheen observed when boat reversed. • C5 Boat launch, observed sheen sweep boat deploying. • MP15.5 North end of south Mill Pond: observed sheen flowing out into the river. • MP15.5: Observed sheen sweep boat operating in the area of sheen sighting. • Morrow Lake: observed sweep boat operating in the southeast corner. • Morrow Lake: observed additional sweep boat operating in the northeast cove. • Morrow Lake: sheen observed in the southeast cove. Sweep boat was operating in the area. • Morrow Lake Delta E4 boom system: buoys deployed along the boom. • Morrow Lake Delta E4 boom system: new boom installed along the northern shore. • Morrow Lake: sheen observed along the northern shoreline near newly installed boom. Sheen sweep boat operating in the Delta. • Morrow Lake Delta: observed sheen sweep boat operating along the southern shoreline. • Morrow Lake Delta: observed crew installing E4 boom system anchor in the southeast corner of Delta. • Morrow Lake Delta: observed sheen in the southeast corner of Delta. Sheen sweep boat was operating in the Delta. • Morrow Lake Delta E4 boom system: Buoys being deployed around the boom. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				