

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/16/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 07/12/12 – 0700, 07/19/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
0900	<p>Operational status:</p> <ul style="list-style-type: none"> • Morrow Lake: sheen observed between Rowe Island and the small island the E4.5 Boom was previously anchored to. • Morrow Lake: poling crew observed on the southwest corner of the lake. • MP36.10 Sediment Trap: monitoring team observed. • Morrow Lake Delta: observed crew preparing to perform a video inspection of the containment curtain. • Morrow Lake Delta: observed crew performing a video inspection of the containment curtain. • Morrow Lake Delta: observed a sweep boat operating along containment boom. • Sheen observed on eastern and western side of Custer Road Bridge, just upstream from MP 21.5 oxbow. Operations was notified. • Sheen sweep boat operating at MP15.5 Mill Ponds. • MP15.5 South Mill Pond: sheen observed in river channel, sweep boat was operating in the area. • Sheen observed within the South Mill Pond. • Sheen observed accumulating at the Paddlers Grove handicap boat launch. • Ceresco Dam Portage work continued. • Ceresco Dam: sheen observed within the downstream Portage cove. • Sheen observed collecting within the boom at Ceresco Dam • Ceresco Dam: sediment plume observed going over the dam. • Ceresco Dam: containment boom. • Ceresco Dam RDB: sheen observed at the top end of boom. • C0.4 Boat launch: observed boom maintenance crew heading back out to clean the boom. • MP5.63 LDB Railroad Crossing: sheen observed. • C0.4 Boat launch observed containment branch collecting temp. • MP5.5 LDB: sheen observed, operations was notified. • Talmadge Creek: restoration work observed. • Source Area Pond: observed crew locating and staking the pipeline. • Source area nearly completely dry. 			
	Additional observations: None			
1500	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				