

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/06/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Isaac Aboulafia, Planning Section Chief		6. Operational Period 0700, 09/6/12 – 0700, 09/13/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0930	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Observed sheen and tar globules along LDB across from C0.4 boat launch. • Observed sheen and tar globules in river channel near trestle at MP 5.75. • Observed sheen and tar globules within containment at control point above Ceresco Dam. • Observed crew removing debris from control point above Ceresco Dam. • Observed sediment trap at MP 10.75 LDB, no sheen observed. • Observed shoreline restoration activities along LDB at Raymond Road. Crews were placing stone along shoreline on west side of Raymond Road. • Observed sediment trap survey crew operating in Mill Ponds. Sheen observed in north end of Mill Ponds near culverts and along south side of Burnham Street Bridge. • Observed crews removing debris from boom configuration C in Morrow Lake Delta and E4.0 containment boom. • Observed Morrow Lake monitoring crew conducting poling in southwestern corner of Morrow Lake. • Observed sheen sweeper boat operating in northern cove of Morrow Lake. 			
	Additional observations: None			
1420	Complete ground survey at E4.0 boat launch, return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				