

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/14/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 09/13/12 – 0700, 09/20/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Leader	Houston, TX	
8. Activity Log			
Time	Major Events		
0900	Boat safety briefing at C0.4 boat launch. Launch. Operational status: • Sheen and tar globules observed at MP5.15 LDB • Sheen and tar globules observed at MP5.20 LDB. • Sheen and tar globules observed at MP5.25 LDB. • MP5.5 LDB sheen and tar globs observed. • MP5.63 LDB at the railroad trestles sheen observed. • MP5.63 LDB below the railroad trestles sheen and tar globs observed. • CSD observed above Ceresco Dam. • Ceresco Dam observed a crew performing boom maintenance. • Observed sheen and tar globs observed collecting along the Ceresco Dam control point boom. • MP5.55 RDB sheen and tar globs observed. • MP5.0 – MP5.15 RDB sheen and tar globs observed. • MP28.25 Oxbow observed a crew reinstalling the CSD. • MP28.25 RDB sheen observed around the boat. The sediment was agitated when docking to observe the work. • MP30.8 LDB observed a Bathymetry survey. • Observed the sweep boat operating between MP21.5 – MP30.8. • MP36.0 LDB ERO work site. • Morrow Lake Delta observed crews performing Bathymetry surveying. • Morrow Lake Delta Boom F observed a crew performing boom and curtain inspection. • Morrow Lake south cove observed a poling crew. • Morrow Lake north cove a poling crew.		

	Additional observations: None
1630	Complete ground survey at E2.0 boat launch, return to ICP.
9. Planning Functions	
• Situational Report. • Updated the schedule. • Assisted with presentation updates.	
10. Prepared by (Name and Position)	
Matthew Haak, Situation Unit Leader, USEPA-START	