

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/15/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 09/13/12 – 0700, 09/20/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Sheen and tar globs observed at the C0.4 boat launch. • MP5.15 LDB sheen observed. Ribbons of sheen and tar globs were observed between MP5.15 – MP5.63 LDB. • MP5.25 LDB sheen observed. Ribbons of sheen and tar globs were observed between MP5.15 – MP5.63 LDB. • MP5.35 LDB sheen observed. Ribbons of sheen and tar globs were observed between MP5.15 – MP5.63 LDB. • MP5.45 LDB sheen observed. Ribbons of sheen and tar globs were observed between MP5.15 – MP5.63 LDB. • MP5.55 LDB sheen observed. Ribbons of sheen and tar globs were observed between MP5.15 – MP5.63 LDB. • Observed the boom maintenance crew arriving to work on the control point boom at Ceresco Dam. • Sheen and tar globs observed collecting along the Ceresco Dam control point boom. • Sheen and tar globs observed collecting along the Ceresco Dam control point boom. • MP15.5 Burnham Street Bridge no sheen observed. • MP21.5 Custer Drive Bridge no sheen observed. • MP26.0 RDB sediment trap installed. • Sheen sweep boat operating between MP21.5 – MP30.8. Observed the sheen sweep boat at MP25.0. • MP23.15 RDB observed sheen and tar globs. The quantity of sheen would not warrant a sweep boat. • MP30.8 LDB no sheen observed. • MP36.0 LDB ERO work site. • Morrow Lake southern cove. Observed sheen and tar globs. • Morrow Lake Delta Boom E observed sheen collecting along the boom. 			

	Additional observations: None
1630	Complete ground survey at Shady Bend Campground boat launch, return to ICP.
9. Planning Functions	
<ul style="list-style-type: none">· Situational Report.· Updated the schedule.· Assisted with presentation updates.	
10. Prepared by (Name and Position)	
Matthew Haak, Situation Unit Leader, USEPA-START	