

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/18/2012	3. Time Prepared 1900
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 09/13/12 – 0700, 09/20/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch. Launch. Boat had mechanical problems, a new boat was dispatched to come take me out.</p> <p>Operational status:</p> <ul style="list-style-type: none"> · Observed the boom maintenance/sweep boat returning from the Ceresco Dam control point boom. · MP5.63 LDB observed sheen and tar globs. · MP5.75 area where sheen and tar globs were observed. Sheen and tar globs appear to have been agitated by the sweep/maintenance boat. · MP21.5 Sediment Trap Bathymetry survey crew observed. · MP28.25 Sediment Trap Bathymetry survey crew observed. · Morrow Lake Delta Bathymetry survey crew observed. · Morrow Lake Delta MP37.75 sheen observed around the Bathymetry survey crew boats. · Morrow Lake Delta observed a crew performing boom/curtain camera inspections. · MP36.1 Sediment trap observed a crew performing Bathymetry survey. 			
	· Additional observations: None			
1630	Complete ground survey at Shady Bend Campground boat launch, return to ICP.			
9. Planning Functions				
· Assisted with presentation updates.				
10. Prepared by (Name and Position)				
Matthew Haak, Situation Unit Leader, USEPA-START				